

September 25, 1891 Constitution - Grounded at entrance of canal, parting tow line; also leaking. Telephoned for tug, ran hawsers, and pumped her out.

Monitor - Belonged to same tow as the Constitution. Same service as given that vessel.